

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/26	MAKE	CAT	MODEL	313CCR
SERIAL	CAT0313CHHGF01827			STAMP	CAT0313CHHGF01827
HR METER	2498 + 3162	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA ☒ YES · NO MAIN PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn OPERATING SYSTEM Swing ☒ FAIR · Attn Travel ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. ☒ CLEAN · FAIR · DIRTY Operator's Seat ☒ FAIR · Attn Glasses ☒ FAIR · Attn AirCon ☒ A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom ☒ FAIR · Attn Boom Cylinder FAIR · ☒ Attn *1 Arm ☒ FAIR · Attn Arm Cylinder ☒ FAIR · Attn BKT ☒ FAIR · Attn BKT Cylinder ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4 COMMENT 左トラックローラー1つ欠 SOME LEFT TRACK ROLLER: MISSING ピンブッシュ割れあり SOME PIN BUSH: BROKEN BKT ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER () Lever LONG · ☒ WRIST Multi ☒ MULTI · 2 · NO ARM-CRANE YES · ☒ NO BLADE YES · ☒ NO OFFSET YES · ☒ NO OFFSET Cylinder FAIR · Attn Piping ☒ YES · NO Breaker only ☒ Multi COMMENT A/C冷えない A/C: MALFUNCTION *1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4
--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。