INSPECTION SHEET 検品書 GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE		2025/7/15		CATEGORY		GENERATOR COMPRESSOR WELDER					
MAKE		KOMATSU				MODEL	EC35SSB-5				
SERIAL	3669053					STAMP	NOT FOUND				
HR METER		2693	HR	TIRE SIZE				YEAR			YR
ENGINE :	MOE	DEL		3LD1		S/N					
Oil leakage	FAIR · Attn	*1				Oil	FAIR • Attn				
Blow-By	FAIR · Attn	A LITTLE • MIDDLE • SEVERE			Exhaust Color	FAIR • Attn					
Sound	FAIR · Attn					Radiator	FAIR • Attn				
GENERAT	OR										
RATED F	POWER	KVA			VA	Leaking Break	er Condition	FAIR •	Attn		
RATED AMPERE		A			Α	Insulation	Condition	FAIR •	Attn		
Output Terminal		FAIR • Attn		-					•		
COMPRES	SOR	_	_								
RATED PR		7			Kgf/cm2	Unload Condition (FAIR)			Attn		
RATED AI	R FLOW		3.7 r			Receiver Tank Condition FAIR - Attn			Attn		
Compressor Oil Leak		FAIR • Attn	R Attn			Safety Valve	e Condition	FAIR •	Attn		
CONDI	TION	FAIR • Attn									
	•	\smile									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 TIRE WEAR FAIR • WORN • UNEVEN WEAR											
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) COMMENTS					2	TIRE WEA	IK FA	πκ • M	OKN '	UNEVE	N WEAK
		一破埍あり	MUFFI FR	CHAMBER:	BROKE	-N					
*1 ヘッドカバー周り油漏れ小 AROUND HEAD COVER: OIL LEAKING											
ļ											

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。