

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/20	MAKE	KOMATSU	MODEL	PC228US-3
SERIAL	21580			STAMP	PC228-021580
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE		COMMENT	
Sound	FAIR • Attn				
Oil	FAIR • Attn				
Exhaust Color	FAIR • Attn				
US EPA	YES • NO				
MAIN PUMP				BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Sound	FAIR • Attn			Lever	LONG • WRIST
Oil leakage	FAIR • Attn			Multi	MULTI • 2 • NO
Power	FAIR • Attn			ARM-CRANE	YES • NO
COOLING SYSTEM				BLADE	YES • NO
Radiator	FAIR • Attn			OFFSET	YES • NO
Oil Cooler	FAIR • Attn			OFFSET Cylinder	FAIR • Attn
OPERATING SYSTEM				Piping	YES • NO Breaker only • Multi 3
Swing	FAIR • Attn	ガタあり LOOSE		COMMENT	
Travel	FAIR • Attn	息つきあり BRIEFLY STOPPING EACH 2 or 3m		スイベル付近より油漏れ大あり ホース？	
INTERIOR See Photos. 写真参照				AROUND SWIVEL JOINT: SEVERE OIL LEAKING HOSE?	
INTERIOR COND.	CLEAN • FAIR • DIRTY			A/Cベルト鳴きあり A/C BELT: NOISES	
Operator's Seat	FAIR • Attn	破れ大あり HUGE CUTS		ドアアウターハンドル破損あり OUTSIDE DOOR HANDLE: BROKEN	
Glasses	FAIR • Attn	ドア下部欠 LOWER DOOR GLASS: MISSING			
AirCon	A/C • H/C • H only • C only • None				
BOOM / ARM / BKT					
Boom	FAIR • Attn	ガタあり、亀裂あり LOOSE, CRACKED			
Boom Cylinder	FAIR • Attn	左油漏れあり LIFT: OIL LEAKING			
Arm	FAIR • Attn				
Arm Cylinder	FAIR • Attn				
BKT	FAIR • Attn	ガタあり LOOSE			
BKT Cylinder	FAIR • Attn	ロッドきずあり ROD: SCRATCHED		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。