

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/24	MAKE	KOBELCO	MODEL	SK200-9
SERIAL	YN13-70195		STAMP	YN13-70195	
HR METER	10829	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	790G	

ENGINE : MODEL		J05E	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT 					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (WRIST)				
Multi	(MULTI) ▪ 2 ▪ NO				
ARM-CRANE	(YES) ▪ NO	フック欠 NO HOOK			
BLADE	YES ▪ (NO)				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)			
COMMENT P200Cエラー表示あり "P200C" ERROR DISPLAY 					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。