

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/9	MAKE	KOMATSU	MODEL	515
SERIAL	10284	STAMP	515-10284		
HR METER	751	HR	Odometer	55323	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	18.4-24	10PR
YEAR	1978	YR			

ENGINE : MODEL	DA640	S/N	543370
Oil leakage	FAIR	Attn	E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL			
T/M TYPE	PS	DD	
Transmission	FAIR	Attn	オイルが入っていない NO OIL
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	効き弱い BRAKE: LOOSE
PARKING BRAKE	FAIR	Attn	効き弱い BRAKE: LOOSE

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり LEFT ARMREST: CUTS
Glasses	FAIR	Attn	Fヒビ割れあり WINDSHIELD: CRACKED
AirCon	A/C	H/C	H only C only None

FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR • WORN • UNEVEN WEAR

COMMENT	
リアシャフト外れ、デフ油漏れあり	
REAR SHAFT: COME OFF, REAR DIFFERENTIAL GEAR: OIL LEAKING	
下周り油漏れあり BOTTOM: OIL LEAKING	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING
RIDE CONTROL	YES ▪ (NO)

ATTACHMENTS			
STD BKT	YES	OTHER	
BLADE	YES	NO	Piping for Tilt YES NO

COMMENT	デフアクスルオイル入っていない NO DIFFERENTIAL OIL
機体外装リペイントあり REPAINTED	
作業機コントロールバルブ付近ホース油漏れあり	
MANY HOSES AROUND CONTROL VALVE: OIL LEAKING	
タコメーター TACHOMETER: 4387km	
燃料メーター不良 FUEL GAUGE: MALFUNCTION	
トランスミッションカップリング、リアデフヨーク改造あり	
(長時間E/Gかけられない)	
TRANSMISSION COUPLING & REAR DIFFERENTIAL YOKE: MODIFIED,	
(ENGINE: UNABLE TO KEEP RUNNING FOR LONG TIME)	
負荷かけるとE/G止まる	
ENGINE STALLING WITH ENGINE LOAD INCREASING	
下周り油漏れあり BOTTOM: OIL LEAKING	
タイヤチェーン4本あり 4 SET OF TIRE CHAINS: PUTTING IN BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。