

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/4	MAKE	MITSUBISHI	MODEL	MM40CR
SERIAL	E1H00430			STAMP	E1H00430
HR METER	3771	HR	YEAR	1998	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	*1
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり CUTS
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	油漏れ、サビあり OIL LEAKING. RUSTY
Arm	FAIR • Attn	ガタあり LOOSE
Arm Cylinder	FAIR • Attn	油漏れあり OIL LEAKING
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左右シューたるみあり TRACK LINKS: WORN	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
スイングシリンダーサビあり SWING CYLINDER: RUSTY	
スイングペダル固着ぎみ SWING PEDAL: A LITTLE STUCK	
下周りにじみあり BOTTOM: OIL OOZING	
ドア上部ローラー外れあり	
UPPER GUIDE ROLLER OF DOOR: COME OFF	
*1 低圧ホース、ポンプ周りにじみあり	
*1 LOW PRESSURE HOSE & AROUND PUMP: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。