

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/3	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	24912		STAMP	KMTPC189A01024912	
HR METER	7370	HR	YEAR	2010	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL 4D95LE S/N 510804

Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	変形あり BACKREST FRAME: DISTORTED
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

右シューたるみあり RIGHT TRACK LINKS: WORN

BKT	STD	SLOPE	NARROW	SKELETON	OTHER ()
-----	-----	-------	--------	----------	-----------

Lever	LONG	WRIST	
-------	------	-------	--

Multi	MULTI	2	NO
-------	-------	---	----

ARM-CRANE	YES	NO	
-----------	-----	----	--

BLADE	YES	NO	
-------	-----	----	--

OFFSET	YES	NO	
--------	-----	----	--

OFFSET Cylinder	FAIR	Attn	
-----------------	------	------	--

Piping	YES	NO	Breaker only Multi
--------	-----	----	--------------------

COMMENT

コントロールバルブ付近にじみあり

AROUND CONTROL VALVE: OIL OOZING

モニター: A/Cエラー表示あり A/C ERROR DISPLAY

A/Cぬるい A/C: MALFUNCTION

*1 ヘッドカバーにじみあり HEAD COVER: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。