

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/3	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	30732		STAMP	KMTPC189E01030732	
HR METER	7623	HR	YEAR	2013	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		4D95LE-5	S/N	542538
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE	MIDDLE SEVERE
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	穴あり HOLES	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
BKT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos.		写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3	
COMMENT									
左右トラックローラー2個破損あり									
SOME TRACK ROLLER EACH TRACK: BROKEN									
BKT	(STD)	/	SLOPE	/	NARROW	/	SKELETON	/	OTHER()
Lever	LONG	▪	(WRIST)						
Multi	MULTI	▪	2	▪	(NO)				
ARM-CRANE	(YES)	▪	NO						
BLADE	YES	▪	(NO)						
OFFSET	YES	▪	(NO)						
OFFSET Cylinder	FAIR	▪	Attn						
Piping	YES	▪	(NO)	Breaker only		▪	Multi		
COMMENT									
コントロールバルブ付近にじみあり									
AROUND CONTROL VALVE: OIL OOZING									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。