

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/5	MAKE	HITACHI	MODEL	ZX75US-5B
SERIAL	HCMDEPA0C00074769		STAMP	HCMDEPA0C00074769	
HR METER	6012	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
MAIN PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	☒ FAIR · Attn	
Boom Cylinder	☒ FAIR · Attn	
Arm	☒ FAIR · Attn	
Arm Cylinder	☒ FAIR · Attn	
BKT	☒ FAIR · Attn	
BKT Cylinder	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	YES · ☒ NO
BLADE	☒ YES · NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。