

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/7/15	CATEGORY	自走式破砕機 MOBILE CRUSHER		
MAKE	KOMATSU		MODEL	BR380JG-1E0	
SERIAL	2772		STAMP	NOT FOUND	
HR METER	7442	HR	Odometer	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP NONE		SHOE	500G	TIRE

ENGINE	MODEL 6D107E-1	S/N 26614830	
Oil leakage	FAIR ・ Attn	Oil	FAIR ・ Attn
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA	YES ・ NO

CONDITION	FAIR ・ Attn
クラッシャーシリンダー油汚れあり CRUSHER CYLINDER: OIL STAINS	
磁選機コンベアベルトひび割れあり CONVEYOR BELT FOR MAGNETIC SEPARATOR: CRACKED	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
付属品: 部材一式 SOME PARTS AS SPARE			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。