

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |      |       |                   |
|-----------------|----------------------------------------|------|------|-------|-------------------|
| INSPECTION DATE | 2025/7/30                              | MAKE | CAT  | MODEL | 320DRR-E          |
| SERIAL          | CAT0320DLRBL00197                      |      |      | STAMP | CAT0320DLRBL00197 |
| HR METER        | 14565 / UNKNOWN                        | HR   | YEAR | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 600G              |

|                |      |          |
|----------------|------|----------|
| ENGINE : MODEL | S/N  | GDC01719 |
| Oil leakage    | FAIR | Attn     |
| Blow-By        | FAIR | Attn     |
| Sound          | FAIR | Attn     |
| Oil            | FAIR | Attn     |
| Exhaust Color  | FAIR | Attn     |
| US EPA         | YES  | NO       |

| MAIN PUMP   |           |                  |
|-------------|-----------|------------------|
| Sound       | FAIR・Attn |                  |
| Oil leakage | FAIR・Attn | にじみあり OIL OOZING |
| Power       | FAIR・Attn |                  |

| COOLING SYSTEM |      |      |
|----------------|------|------|
| Radiator       | FAIR | Attn |
| Oil Cooler     | FAIR | Attn |

| OPERATING SYSTEM |             |                   |
|------------------|-------------|-------------------|
| Swing            | FAIR · Attn | ガタあり SWING: LOOSE |
| Travel           | FAIR · Attn |                   |

| INTERIOR        |       | See Photos. 写真参照 |                    |
|-----------------|-------|------------------|--------------------|
| INTERIOR COND.  | CLEAN | FAIR             | DIRTY              |
| Operator's Seat | FAIR  | Attn             | 破れあり TORN          |
| Glasses         | FAIR  | Attn             | *1                 |
| AirCon          | A/C   | H/C              | H only C only None |

| BOOM / ARM / BKT |      |      |
|------------------|------|------|
| Boom             | FAIR | Attn |
| Boom Cylinder    | FAIR | Attn |
| Arm              | FAIR | Attn |
| Arm Cylinder     | FAIR | Attn |
| BKT              | FAIR | Attn |
| BKT Cylinder     | FAIR | Attn |

|                                                              |                  |
|--------------------------------------------------------------|------------------|
| UNDERCARRIAGE :                                              | See Photos. 写真参照 |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3                |

|               |                                 |
|---------------|---------------------------------|
| COMMENT       |                                 |
| シュープレートガタあり   | SOME SHOE PLATES: LOOSE         |
| 底板周り油汚れ、油漏れあり | BOTTOM: OIL STAINS, OIL LEAKING |

|                 |       |       |              |          |       |
|-----------------|-------|-------|--------------|----------|-------|
| BKT             | STD   | SLOPE | NARROW       | SKELETON | OTHER |
| Lever           | LONG  | WRIST |              |          |       |
| Multi           | MULTI | 2     | NO           |          |       |
| ARM-CRANE       | YES   | NO    |              |          |       |
| BLADE           | YES   | NO    |              |          |       |
| OFFSET          | YES   | NO    |              |          |       |
| OFFSET Cylinder | FAIR  | Attn  |              |          |       |
| Piping          | YES   | NO    | Breaker only | Multi    |       |

|                                               |                               |
|-----------------------------------------------|-------------------------------|
| COMMENT                                       |                               |
| 下側HRメーター不良                                    | ONE OF HR METERS: MALFUNCTION |
| A/Cベルト欠                                       | A/C: NO BELT                  |
| *1 F下部フレームサビで穴あり                              |                               |
| *1 LOWER WINDSHIELD FRAME: RUSTY & HUGE HOLES |                               |

|                                                                      |   |
|----------------------------------------------------------------------|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |
|----------------------------------------------------------------------|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。