

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/3	MAKE	CAT	MODEL	950H
SERIAL	CAT0950HAJ5J02031			STAMP	CAT0950HAJ5J02031
HR METER	7746	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25 20PR

ENGINE : MODEL C7 S/N KHX48479	
Oil leakage	FAIR · ☒ Attn *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ Attn
Oil	☒ Attn
Exhaust Color	☒ Attn
US EPA	YES · ☒ NO
OPERATION PUMP	
Sound	☒ Attn
Oil leakage	☒ Attn
Power	☒ Attn
COOLING SYSTEM	
Radiator	☒ Attn
Oil Cooler	☒ Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	☒ Attn
Travel	☒ Attn
FOOT BRAKE	☒ Attn
PARKING BRAKE	☒ Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ Attn
Glasses	☒ Attn
AirCon	☒ A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	☒ Attn
Bell crank	☒ Attn
Bucket	☒ Attn
Articulate	☒ Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES · NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
*1 ヘッドカバー、下側にじみあり	
*1 HEAD COVER & BOTTOM OF ENGINE: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。