

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/17	MAKE	CAT	MODEL	938F
SERIAL	8SM00897			STAMP	8SM00897
HR METER	ERROR	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL		S/N	1CK13324
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS	DD	
Transmission	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn	破れあり CUTS
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C • H only • C only • None	
FRONT & CYLINDERS			
Arm	☒ FAIR	Attn	
Bell crank	☒ FAIR	Attn	
Bucket	☒ FAIR	Attn	
Articulate	FAIR	☒ Attn	*1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES • ☒ NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
*1 右シリンダーにじみ、ガタあり RIGHT CYLINDER: OIL OOZING, LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。