

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/4	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	82127		STAMP	KMTPC202P01082127	
HR METER	6738 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		4D95LE-5	S/N	558335
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING	
BKT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE		
左ピンブッシュ割れあり SOME LEFT PIN BUSH: BROKEN		
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())	
Lever	LONG ▪ (WRIST)	
Multi	(MULTI) ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ (NO)	
BLADE	YES ▪ (NO)	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ (NO)	Breaker only ▪ Multi
COMMENT		
A/Cベルト鳴きあり A/C BELT: NOISES		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。