INSPECTION SHEET 検品書 OTHER その他

| INSPECTIO | N DATE | 2025/7/11 | CA | ΓEGORY | 充電式手押 | し除雪機 | 雪機 WALK-BEHIND BATTERY SNOW PLO | |
|--|--|----------------------------|----------------|--------|-------------------------------------|-------------|---------------------------------|--|
| MAKE | KOSHIN | | | | MODEL | SR-350 | | |
| SERIAL | NO PLATE | | | | STAMP | NOT FOUND | | |
| HR METER | UNKNOWN HR Odometer | | | | km YEAR | | YR | |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNR / NONE) SHOE 120R TIRE | | | | | | | |
| ENGINE | MODEL S/N | | | | | | | |
| Oil leakage | FAIR · Attn | | | | Oil | FAIR • Attn | | |
| Blow-By | FAIR · Attn A LITTLE • MIDDLE • SEVERE | | | | Exhaust Color | FAIR • Attn | | |
| Sound | FAIR · Attn | | | | EPA | YES • NO | | |
| CONDITION (FAIR) - Attn | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| UNDERCARRIAGE: See Photos. 写真参照 | | | | | | | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | | | TIRE WEAR FAIR • WORN • UNEVEN WEAR | | | |
| COMMENT | | | | | | | | |
| 充電コード、取扱説明書あり W/CHARGING CABLE & MANUAL BOOK | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| RUST of BODY | 5: NONE, 4: A | LITTLE, 3: MIDDLE, 2: MUCH | , 1: CORRODED) | 5 | | | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。