

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/10	MAKE	CAT	MODEL	938M
SERIAL	CAT0938MJJ3R02986			STAMP	CAT0938MJJ3R02986
HR METER	11138	HR	Odometer	19375	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	20.5R25		

ENGINE : MODEL		C7.1	S/N	D8T19141
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	☐ NO		
OPERATION PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	☒ PS	☐ DD		
Transmission	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
FOOT BRAKE	☒ FAIR	Attn		
PARKING BRAKE	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY		
Operator's Seat	☒ FAIR	Attn		
Glasses	☒ FAIR · ☒ Attn	F割れあり UPPER WINDSHIELD: CRACKED		
AirCon	☒ A/C ·	☐ H/C · ☐ H only · ☐ C only · ☐ None		
FRONT & CYLINDERS				
Arm	☒ FAIR · ☒ Attn	*1		
Bell crank	☒ FAIR	Attn		
Bucket	☒ FAIR	Attn		
Articulate	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · ☒ WORN · ☐ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES · ☐ NO
ATTACHMENTS	
STD BKT	☒ YES · ☐ OTHER
BLADE	☒ YES · ☐ NO Piping for Tilt ☐ YES · ☒ NO
COMMENT	
バックカメラ不良 BACK MONITOR: MALFUNCTION	
*1 左側シリンダーにじみあり LEFT CYLINDER: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。