

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/29	MAKE	YANMAR	MODEL	B50
SERIAL	UNREADABLE		STAMP	00933B	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	380G	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · (DIRTY)	
Operator's Seat	FAIR · (Attn)	骨組みのみあり BROKEN (ONLY FRAME)
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	FAIR · (Attn)	油漏れあり OIL LEAKING
Arm	(FAIR) · Attn	
Arm Cylinder	FAIR · (Attn)	油漏れ小 OIL LEAKING
BKT	FAIR · (Attn)	*1
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
足元全体摩耗大 TRACK LINKS & SHOE PLATES: MUCH WORN		
一部下部フレーム穴あり LEFT TRACK FRAME: HOLES		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	(LONG) · WRIST	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	(YES) · NO	変形大 DEFORMED
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi
COMMENT		
計器類全部故障あり ALL METERS: MALFUNCTION		
*1 コンクリート付着大、ガタ大 MUCH CONCRETE STAINS, MUCH LOOSE		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。