

**INSPECTION SHEET 検品書**  
**OTHER その他**

INSPECTION DATE	2025/8/29	CATEGORY	除雪機 SNOWMATE (SNOW BLOWER)		
MAKE	YAMAHA		MODEL	YT970ES	
SERIAL	7RW-130133		STAMP	NOT FOUND	
HR METER	UNKNOWN	HR	Odometer	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	130R	TIRE

ENGINE	MODEL	7RJ6	S/N	
Oil leakage	<u>FAIR</u> • Attn		Oil	<u>FAIR</u> • Attn
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE	Exhaust Color	<u>FAIR</u> • Attn
Sound	<u>FAIR</u> • Attn		EPA	YES • <u>NO</u>

CONDITION	<u>FAIR</u> • Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>
---

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
--	---	-----------	---------------------------

<b>COMMENT</b>
機体外装リペイントあり REPAINTED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
--	---	--

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。