

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/15	MAKE	CAT	MODEL	314FCR
SERIAL	CAT0314FERAF10395			STAMP	CAT0314FERAF10395
HR METER	1736 / 1739		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		C4.4	S/N	W7N49616
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD (<u>SLOPE</u>) NARROW / SKELETON / OTHER()	
Lever	LONG ▪ (<u>WRIST</u>)	
Multi	(<u>MULTI</u>) ▪ 2 ▪ NO	
ARM-CRANE	(<u>YES</u>) ▪ NO	
BLADE	YES ▪ (<u>NO</u>)	
OFFSET	YES ▪ (<u>NO</u>)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	(<u>YES</u>) ▪ NO	Breaker only ▪ (<u>Multi</u>)
COMMENT		
E/G関連異常表示あり ENGINE WARNING DISPLAY		
サイドカッターCAB内にあり SIDE CUTTERS: PUTTING IN CAB		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。