

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

|                 |                                        |      |          |           |           |      |    |
|-----------------|----------------------------------------|------|----------|-----------|-----------|------|----|
| INSPECTION DATE | 2025/7/10                              | MAKE | HITACHI  | MODEL     | ZW310-A   |      |    |
| SERIAL          | RYU4HD00L00006354                      |      |          | STAMP     | S58-06354 |      |    |
| HR METER        | 14639                                  | HR   | Odometer | 66418     | km        | YEAR | YR |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |          | TIRE SIZE | 26.5-25   |      |    |

|                                  |       |                                  |
|----------------------------------|-------|----------------------------------|
| <b>ENGINE : MODEL</b>            |       | <b>S/N</b>                       |
| Oil leakage                      | FAIR  | Attn                             |
| Blow-By                          | FAIR  | Attn A LITTLE · MIDDLE · SEVERE  |
| Sound                            | FAIR  | Attn                             |
| Oil                              | FAIR  | Attn                             |
| Exhaust Color                    | FAIR  | Attn                             |
| US EPA                           | YES   | NO                               |
| <b>OPERATION PUMP</b>            |       |                                  |
| Sound                            | FAIR  | Attn                             |
| Oil leakage                      | FAIR  | Attn                             |
| Power                            | FAIR  | Attn                             |
| <b>COOLING SYSTEM</b>            |       |                                  |
| Radiator                         | FAIR  | Attn                             |
| Oil Cooler                       | FAIR  | Attn                             |
| <b>TRANSMISSION &amp; TRAVEL</b> |       |                                  |
| T/M TYPE                         | PS    | DD                               |
| Transmission                     | FAIR  | Attn                             |
| Travel                           | FAIR  | Attn                             |
| FOOT BRAKE                       | FAIR  | Attn                             |
| PARKING BRAKE                    | FAIR  | Attn                             |
| <b>INTERIOR See Photos. 写真参照</b> |       |                                  |
| INTERIOR COND.                   | CLEAN | FAIR · DIRTY                     |
| Operator's Seat                  | FAIR  | Attn                             |
| Glasses                          | FAIR  | Attn *1                          |
| AirCon                           | A/C   | H/C · H only · C only · None     |
| <b>FRONT &amp; CYLINDERS</b>     |       |                                  |
| Arm                              | FAIR  | Attn 左側フレーム補修跡あり FRAME: REPAIRED |
| Bell crank                       | FAIR  | Attn                             |
| Bucket                           | FAIR  | Attn                             |
| Articulate                       | FAIR  | Attn                             |

|                                                                      |                                   |
|----------------------------------------------------------------------|-----------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                 |
| TIRE WEAR                                                            | FAIR · WORN · UNEVEN WEAR         |
| <b>COMMENT</b>                                                       |                                   |
| STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING     |                                   |
| RIDE CONTROL                                                         | YES · NO                          |
| <b>ATTACHMENTS</b>                                                   |                                   |
| STD BKT                                                              | YES · OTHER ログフォーク LOG FORK       |
| BLADE                                                                | YES · NO Piping for Tilt YES · NO |
| <b>COMMENT</b>                                                       |                                   |
| *1 ドア下部ひび割れ大                                                         |                                   |
| *1 LOWER DOOR GLASS: CRACKED, COVERED WITH ADHESIVE TAPES            |                                   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                   |
| 4                                                                    |                                   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。