

**INSPECTION SHEET 検品書**  
**OTHER その他**

|                 |                                             |          |                       |            |         |
|-----------------|---------------------------------------------|----------|-----------------------|------------|---------|
| INSPECTION DATE | 2025/7/14                                   | CATEGORY | 自動式破砕機 MOBILE CRUSHER |            |         |
| MAKE            | KOMATSU                                     |          | MODEL                 | BR350JG-1E |         |
| SERIAL          | 1432                                        |          | STAMP                 | NOT FOUND  |         |
| HR METER        | 8297                                        | HR       | Odometer              | km         | YEAR YR |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP <u>NONE</u> |          | SHOE                  | 500G       | TIRE    |

|             |                                               |                                  |
|-------------|-----------------------------------------------|----------------------------------|
| ENGINE      | MODEL                                         | S/N                              |
| Oil leakage | <u>FAIR</u> ・ Attn                            | Oil <u>FAIR</u> ・ Attn           |
| Blow-By     | <u>FAIR</u> ・ Attn A LITTLE ・ MIDDLE ・ SEVERE | Exhaust Color <u>FAIR</u> ・ Attn |
| Sound       | <u>FAIR</u> ・ Attn                            | EPA YES ・ <u>NO</u>              |

|           |                    |
|-----------|--------------------|
| CONDITION | <u>FAIR</u> ・ Attn |
|           |                    |

|                                         |
|-----------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b> |
|-----------------------------------------|

|                                                              |   |           |                           |
|--------------------------------------------------------------|---|-----------|---------------------------|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | TIRE WEAR | FAIR ・ WORN ・ UNEVEN WEAR |
|--------------------------------------------------------------|---|-----------|---------------------------|

|                                                  |
|--------------------------------------------------|
| <b>COMMENT</b>                                   |
| ラジエータ目詰まりあり RADIATOR: CLOGGED                    |
| コンベア後方上下用シリンダーサビあり REAR CONVEYOR CYLINDER: RUSTY |
|                                                  |
|                                                  |
|                                                  |
|                                                  |
|                                                  |
|                                                  |
|                                                  |

|                                                                      |   |
|----------------------------------------------------------------------|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |
|----------------------------------------------------------------------|---|

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。