

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	KOBELCO	MODEL	RK500-2
SERIAL No.	PLATE : ET06-10045		STAMP : ET06-10045		
HR METER	28635	HR	Odometer	15372	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	3 GEAR	
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	5		SECTIONS		
CRACK/ENFORCEMENT	(FAIR)	▪ Attn			
DERRICKING CYL.	FAIR	▪ (Attn)	自然降下あり HYDRAULIC DRIFT		
EXTENSION CYL.	(FAIR)	▪ Attn			
JIB	(YES)	▪ NO			
JIB TYPE	STD	▪ (PWR)			
MAIN & SUB WIRE	(YES)	▪ NO			
HOO K	25t, BALL, 51t HANGER				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4				
TIRE WEAR	(FAIR)	▪ WORN ▪ UNEVEN WEAR			
COMMENT 					
OUTRIGGERS					
OUTRIGGERS	(X)	▪ H			
OUTRIGGERS COND.	(FAIR)	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT フリーフォール付 FREE FALL: YES 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。