

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/21	MAKE	YANMAR	MODEL	VIO30-6
SERIAL	6L129		STAMP	6L129	
HR METER	1418	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		3TNV88	S/N	166419
Oil leakage	(FAIR)	Attn		
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR)	Attn		
Oil	(FAIR)	Attn		
Exhaust Color	(FAIR)	Attn		
US EPA	YES	(NO)		
MAIN PUMP				
Sound	(FAIR)	Attn		
Oil leakage	(FAIR)	Attn		
Power	(FAIR)	Attn		
COOLING SYSTEM				
Radiator	(FAIR)	Attn		
Oil Cooler	(FAIR)	Attn		
OPERATING SYSTEM				
Swing	(FAIR)	Attn		
Travel	(FAIR)	Attn		
INTERIOR		See Photos. 写真参照		
INTERIOR COND.	(CLEAN)	FAIR	DIRTY	
Operator's Seat	(FAIR)	Attn		
Glasses	(FAIR)	Attn		
AirCon	(A/C)	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	(FAIR)	Attn		
Boom Cylinder	(FAIR)	Attn		
Arm	(FAIR)	Attn		
Arm Cylinder	(FAIR)	Attn		
ATTACHMENT	(FAIR)	Attn		
BKT Cylinder	(FAIR)	Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG	(WRIST)	
Multi	(MULTI)	2	NO
ARM-CRANE	(YES)	NO	
BLADE	(YES)	NO	
OFFSET	YES	(NO)	
OFFSET Cylinder	FAIR	Attn	
Piping	(YES)	NO	Breaker only · Multi
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。