

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/16	MAKE	FURUKAWA	MODEL	FL310-3
SERIAL	RYU4F000V00005412			STAMP	S50-05412
HR METER	6103	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 10PR (SNOW, SPIKE)

ENGINE : MODEL 4BG1 S/N	
Oil leakage	FAIR • ☒ Attn E/G周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn
Oil	☒ FAIR • Attn
Exhaust Color	☒ FAIR • Attn
US EPA	YES • ☒ NO
OPERATION PUMP	
Sound	☒ FAIR • Attn
Oil leakage	☒ FAIR • Attn
Power	☒ FAIR • Attn
COOLING SYSTEM	
Radiator	☒ FAIR • Attn
Oil Cooler	☒ FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS • DD
Transmission	☒ FAIR • Attn
Travel	☒ FAIR • Attn
FOOT BRAKE	☒ FAIR • Attn
PARKING BRAKE	☒ FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	☒ FAIR • Attn
Glasses	☒ FAIR • Attn
AirCon	A/C • H/C • ☒ H only • C only • None
FRONT & CYLINDERS	
Arm	FAIR • ☒ Attn 右シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING
Bell crank	☒ FAIR • Attn
Bucket	FAIR • ☒ Attn シリンダー油漏れあり CYLINDER: OIL LEAKING
Articulate	☒ FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR • ☒ WORN • UNEVEN WEAR
COMMENT	
下周りにじみあり BOTTOM: OIL OOZING	
タコメーター TACHOMETER: 44048km	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES • ☒ NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt ☒ YES • NO
COMMENT	
センターピンガタあり CENTER PIN: LOOSE	
機体外装リペイントあり REPAINTED	
左側バッテリー膨張あり LEFT BATTERY: EXPANDED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。