

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2025/7/17	MAKE	MITSUBISHI	MODEL	MG500-S		
SERIAL	5G100082			STAMP	5G100082		
HR METER	3258	HR	Odometer	26574	km	YEAR	YR
SCARIFIER	YES	NO	BLADE		3960	mm	
CAB/CNP	CAB	CNP	NONE	TIRE SIZE	14.00-24		

ENGINE : MODEL		6D22	S/N	147852
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	YES · (NO)			
OPERATION PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	PS · (DD)			
Transmission	(FAIR) · Attn			
Travel	(FAIR) · Attn			
FOOT BRAKE	(FAIR) · Attn			
PARKING BRAKE	(FAIR) · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · (FAIR) · DIRTY			
Operator's Seat	(FAIR) · Attn			
Glasses	(FAIR) · Attn			
AirCon	A/C · H/C · (H only) · C only · None			
HYD. CYLINDER				
For Blade	FAIR · (Attn) *1			
For Scarifier	FAIR · Attn			
Articulate	FAIR · (Attn) *2			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR
COMMENT	
左サークルリフトシリンダーメッキ剥がれあり LEFT CIRCLE LIFT CYLINDER: COATING PEELED	
サークルスイングシリンダーメッキ剥がれあり CIRCLE SWING CYLINDER: COATING PEELED	
サークル旋回モーター周り油漏れあり AROUND CIRCLE SWING MOTOR: OIL LEAKING	
A/C風が出ない A/C: NOT BLOWING AIR	
*1 右チップシリンダーサビ、スライドシリンダーサビあり、油漏れ小 *1 RIGHT TIP CYLINDER: RUSTY, SLIDE CYLINDER: RUSTY, OIL LEAKING	
*2 左側サビ、右側にじみあり *2 LEFT CYLINDER: RUSTY, RIGHT CYLINDER: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。