

INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2025/7/22	CATEGORY	GENERATOR / COMPRESSOR / WELDER				
MAKE	DENYO		MODEL	DCA-25USI3			
SERIAL	3895526		STAMP	NOT FOUND			
HR METER	4419	HR	TIRE SIZE	-		YEAR	YR

ENGINE :	MODEL	4LE2	S/N	628941
Oil leakage	FAIR · Attn	*1	Oil	FAIR · Attn
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR · Attn
Sound	FAIR · Attn		Radiator	FAIR · Attn

GENERATOR				
RATED POWER	20 / 25	KVA	Leaking Breaker Condition	FAIR ▪ Attn
RATED AMPERE	57.7 / 65.6	A	Insulation Condition	FAIR ▪ Attn
Output Terminal	FAIR ▪ Attn			

COMPRESSOR				
RATED PRESSURE	Mpa Kgf/cm2		Unload Condition	FAIR ▪ Attn
RATED AIR FLOW	m3/min		Receiver Tank Condition	FAIR ▪ Attn
Compressor Oil Leak	FAIR ▪ Attn		Safety Valve Condition	FAIR ▪ Attn

CONDITION	FAIR ▪ Attn

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
---	---	-----------	---------------------------

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。