

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/24	MAKE	FURUKAWA	MODEL	FL120-II
SERIAL	1590	STAMP	F21-1590		
HR METER	7124	HR	Odometer	23917	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	16.9-24	10PR
YEAR		YR			

ENGINE : MODEL		S/N	241861
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	PS	DD	
Transmission	FAIR	Attn	
Travel	FAIR	Attn	*1
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり DAMAGED
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
FRONT & CYLINDERS			
Arm	FAIR	Attn	*2
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	
Articulate	FAIR	Attn	*2

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
機体外装リペイントあり REPAINTED	
ラジオ音出ない RADIO: NOT SPEAKING	
センターピンガタあり CENTER PIN: LOOSE	
*1 パワー弱い、2・3速遅い WEAK POWER, 2nd & 3rd GEARS: SLOW	
*2 右シリンダーにじみあり RIGHT CYLINDER: OIL Oozing	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。