

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/22	MAKE	KOMATSU	MODEL	PC450LC-6
SERIAL	12868			STAMP	KMTPC073J02012868
HR METER	21589	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G PADS

ENGINE : MODEL 6D125E2 S/N 00086426	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE MIDDLE SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn *1
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn *2
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn *3
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn パッチ、溶接跡あり PATCHED, WELDED
Boom Cylinder	FAIR · Attn *4
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn にじみあり OIL OOZING
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
スイベル油汚れあり SWIVEL: OIL STAINS	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
エレベータCAB: 溶接跡あり ELEVATOR CAB: WELDED	
ワンタッチ付 W/ONE-TOUCH	
アタッチメントなし WITHOUT ATTACHMENT	
A/C冷えない A/C: MALFUNCTION	
*1 ブームで本体上がらない UNABLE TO PUSH UP THE BODY BY BOOM	
*2 前後進可能だが片足ずつ走行できない	
*2 UNABLE TO TRAVEL WITH ONE TRACK	
(ABLE TO TRAVEL FORWARD & BACKWARD WITH BOTH TRACKS)	
*3 右側ひび割れあり、アクリル板	
*3 RIGHT SIDE GLASS: ACRYLIC BOARD (CRACKED)	
*4 左右にじみ、右側サビあり	
*4 CYLINDERS: OIL OOZING, RIGHT CYLINDER: RUSTY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。