

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/22	MAKE	HITACHI	MODEL	EX100
SERIAL	NO PLATE		STAMP	1E3P002555	
HR METER	11846	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO

MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR・Attn	ゴリゴリ感、ガタあり RATTLING, SWING: LOOSE
Travel	FAIR・Attn	増速S/W不良 HI/LO SWITCH: MALFUNCTION

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	破れあり CUTS
Glasses	FAIR ・ Attn	*1
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	にじみあり OIL OOZING
Arm	FAIR・Attn	
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	ガタ、ヘコミ、曲がりあり LOOSE, DENT, DISTORTED
BKT Cylinder	FAIR・Attn	メッキ剥れあり COATING: PEELED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT
右側トラックローラー不良あり
SOME RIGHT TRACK ROLLERS: MALFUNCTION

BKT (STD / SLOPE / NARROW / SKELETON / OTHER()

Lever	LONG ▪ WRIST
-------	---------------------

Multi	MULTI • 2 • NO
-------	----------------

ARM-CRANE	YES	☒ NO
-----------	-----	-------------------------------------

BLADE	YES • NO
-------	----------

OFFSET	YES	NO
--------	-----	----

OFFSET Cylinder	FAIR	Attn
-----------------	------	------

Piping	YES	☒ NO	Breaker only	☒ Multi
--------	-----	-------------------------------------	--------------	--

COMMITTEE	DATE	BY	REMARKS

*1 CAB右側、ドア上部:アクリル板加工あり

*1 SOME RIGHT SIDE GLASS & UPPER DOOR GLASSES: ACRYLIC BOARDS

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **3**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。