

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/23	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EJSXE04543		STAMP	CAT0320EJSXE04543	
HR METER	2941 / 2945 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE :	MODEL	C6.6	S/N	C8N38720
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR · Attn	
Travel	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR • Attn	破れあり TINY CUTS			
Glasses	FAIR • Attn				
AirCon	A/C •	H/C •	H only •	C only •	None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	サビあり RUSTY

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
---	----------

COMMENT

右側シューリンク固着あり RIGHT TRACK LINKS: STUCK

BKT	STD (SLOPE) NARROW / SKELETON / OTHER()
-----	--

Lever	LONG ▪ WRIST
-------	---------------------

Multi	MULTI · 2 · NO
-------	-----------------------

ARM-CRANE	YES	☒ NO
-----------	-----	-------------------------------------

BLADE YES • NO

OFFSET	YES • NO
--------	----------

OFFSET Cylinder	FAIR	▪	Attn
-----------------	------	---	------

Piping	☒ YES ▪ NO	Breaker only ▪ ☒ Multi
--------	---	---

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。