

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/7	MAKE	KOBELCO	MODEL	SK200-10
SERIAL	YN15086599			STAMP	YN15086599
HR METER	2584	HR	YEAR	2020	YR
CAB/CNP	☒ ROPS CAB / CAB / ☐ ROPS CNP / CNP / ☐ NONE			SHOE	700G

ENGINE : MODEL		J05E	S/N	UM19809
Oil leakage	☒ FAIR • Attn			
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE		
Sound	☒ FAIR • Attn			
Oil	☒ FAIR • Attn			
Exhaust Color	☒ FAIR • Attn			
US EPA	YES • ☒ NO			
MAIN PUMP				
Sound	☒ FAIR • Attn			
Oil leakage	☒ FAIR • Attn			
Power	☒ FAIR • Attn			
COOLING SYSTEM				
Radiator	☒ FAIR • Attn			
Oil Cooler	☒ FAIR • Attn			
OPERATING SYSTEM				
Swing	☒ FAIR • Attn			
Travel	☒ FAIR • Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY			
Operator's Seat	☒ FAIR • Attn			
Glasses	☒ FAIR • Attn			
AirCon	☒ A/C • H/C • H only • C only • None			
BOOM / ARM / BKT				
Boom	☒ FAIR • Attn			
Boom Cylinder	☒ FAIR • Attn			
Arm	☒ FAIR • Attn			
Arm Cylinder	☒ FAIR • Attn			
BKT	☒ FAIR • Attn			
BKT Cylinder	☒ FAIR • Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	☒ YES • NO
BLADE	YES • ☒ NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	☒ YES • NO Breaker only • ☒ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。