

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/21	MAKE	SUMITOMO	MODEL	SH120-7
SERIAL	SMT120A7K00SC2008			STAMP	SMT120A7K00SC2008
HR METER	2777	HR	YEAR	2020	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		4JJ1	S/N	297344
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	(YES) · NO			
MAIN PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
OPERATING SYSTEM				
Swing	(FAIR) · Attn			
Travel	(FAIR) · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	(CLEAN)	FAIR · DIRTY		
Operator's Seat	(FAIR) · Attn			
Glasses	(FAIR) · Attn			
AirCon	(A/C) · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	(FAIR) · Attn			
Boom Cylinder	(FAIR) · Attn			
Arm	(FAIR) · Attn			
Arm Cylinder	(FAIR) · Attn			
ATTACHMENT	(FAIR) · Attn			
BKT Cylinder	(FAIR) · Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	(YES) · NO	プレート欠 NO PLATE	
BLADE	YES · (NO)		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	(YES) · NO	Breaker only · (Multi)	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。