

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KOBELCO	MODEL	SK135SR-5
SERIAL	YY08042160		STAMP	YY08042160	
HR METER	2851	HR	YEAR	2020	YR
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		4JJ1	S/N	602502
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	☒ CLEAN	FAIR · DIRTY		
Operator's Seat	☒ FAIR	Attn		
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	Attn		
Arm	☒ FAIR	Attn		
Arm Cylinder	☒ FAIR	Attn		
ATTACHMENT	☒ FAIR	Attn		
BKT Cylinder	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only ☒ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。