

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/22	MAKE	KOBELCO	MODEL	SK135SR
SERIAL	YY01-01391		STAMP	YY01-01391	
HR METER	11646	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	穴あり HOLES
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	両側油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照		4
COMMENT		
両側トラックローラー不良あり		
SOME TRACK ROLLERS: MALFUNCTION		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG ▪ (WRIST)	
Multi	(MULTI) ▪ 2 ▪ NO	
ARM-CRANE	(YES) ▪ NO	*1
BLADE	YES ▪ (NO)	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)
COMMENT		
CABへコミあり CAB: DENT		
*1 クレーンモード入らない、		
ディスプレイ文字不鮮明のためエラー表示見えない		
*1 CRANE MODE: UNABLE TO TURN ON,		
SOME ERROR DISPLAY (MONITOR: UNREADABLE)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。