

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/4	MAKE	HITACHI	MODEL	ZX135US-3
SERIAL	HCM1R400C00091408		STAMP	HCM1R400C00091408	
HR METER	6185	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE :		MODEL	4JJ1	S/N	155142
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn	*1		
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ガタあり SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY				
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C ・ H/C ・ H only ・ C only ・ None				
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
BKT	FAIR	Attn			
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE :						See Photos.						写真参照								
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		2		
COMMENT																				
BKT		(STD)	/	SLOPE	/	NARROW	/	SKELETON	/	OTHER(										)
Lever		LONG	▪	(WRIST)																
Multi		MULTI	▪	2	▪	(NO)														
ARM-CRANE		(YES)	▪	NO																
BLADE		YES	▪	(NO)																
OFFSET		YES	▪	(NO)																
OFFSET Cylinder		FAIR	▪	Attn																
Piping		YES	▪	(NO)	Breaker only		▪	Multi												
COMMENT																				
*1 低回転時バケットついて機体上がらない																				
*1 UNABLE TO PUSH UP THE BODY BY BOOM ON LOW ENGINE SPEED																				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。