

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/18	MAKE	HITACHI	MODEL	ZX75US-A
SERIAL	HCM1CG00E00042462			STAMP	HCM1CG00E00042462
HR METER	9050	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G

ENGINE : MODEL		4JG1	S/N	270220
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn	油漏れ小 OIL LEAKING	
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn	ガタあり SWING: LOOSE	
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY		
Operator's Seat	☒ FAIR	Attn		
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C ·	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	Attn		
Arm	☒ FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	☒ FAIR	Attn		
BKT	☒ FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT ☒ STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · Multi 5
COMMENT	
キーシリンダー差し込み緩い(キーONで抜ける)	
KEY CYLINDER: LOOSE TO LOCK THE KEY	
(ABLE TO PULL THE KEY FROM THE CYLINDER	
EVEN AT THE ON POSITION)	
A/C温度下げボタン反応しない、冷えない	
TEMPERATURE CONTROL SWITCH OF A/C: NOT WORKING,	
A/C: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。