## INSPECTION SHEET 検品書 LIFTING PLATFORM 高所作業車

INSPECTION DATE		2025/7/18 MAKE		Ξ	MAEDA			MODEL	HF070R-2			
SERIAL No.	PLATE: 7NU20245						STAMP: NOT FOUND					
HR METER	4278 HR Odometer				•	k	m YEAR		YR			
CHASSIS	SSIS MODEL						No.					
SHOE	230R						TIRE SIZE					
MAX HIGHT	6.8 m					m	MAX WEIGH	ΗT	150 kg			
ENGINE :	MODEL D722 S/N 6U7052						INTERIOR See Photos. 写真参照					
Oil leakage	FAIR) · Attn						INTERIOR COND.	CL	_EAN •	FAIR • DIRTY		
Blow-By	FAIR) · Attn A LITTLE • MIDDLE • SEVERE						Operator's Seat FAIR · Attn					
Sound	FAIR) · Attn						Glasses	FAIR) •	Attn			
Oil	FAIR) · Attn						AirCon (	A/C	) · H/C	- H only - C only -	None	
Exhaust Color	FAIR) · Attn						UNDERCARRIAGE: See Photos. 写真参照					
US EPA	YES (NO)						RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3					
OPERATION PUMP							TIRE WEAR FAIR · WORN · UNEVEN WEAR					
Sound FAIR) · Attn							COMMENT					
Oil leakage	FAIR) · Attn											
Power (FAIR). Attn												
COOLING SYSTEM							OUTRIGGERS X · H					
Radiator	FAIR) · Attn						OUTRIGGERS C	OND.	FAIR • Attn			
Oil Cooler	FAIR · Attn						COMMENT					
TRANSMISSION & TRAVEL												
T/M TYPE	АТ). мт		No.	OF GEARS		GEARS						
Transmission	FAIR) · Attn		ļ									
4WD	4WD • 2WD											
Travel	FAIR) · Attn											
Swing	FAIR · Attn											
FOOT BRAKE	FAIR • Attn											
PARKING BRAKE FAIR · Attn												
воом												
No. of Section SECTIONS												
DERRICKIN	•											
EXTENSIO	N CYL.	FAIR • Attn	R) · Attn					RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。