

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/5	MAKE	KOMATSU	MODEL	PC128US-8
SERIAL	25702		STAMP	KMTPC189J01025702	
HR METER	5358	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL 4D95LE-5 S/N 514155					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	(YES)	NO			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · (DIRTY)				
Operator's Seat	FAIR · (Attn)	破れあり HUGE CUTS			
Glasses	(FAIR) · Attn				
AirCon	(A/C) · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	(FAIR) · Attn				
Boom Cylinder	(FAIR) · Attn				
Arm	(FAIR) · Attn				
Arm Cylinder	(FAIR) · Attn				
BKT	(FAIR) · Attn				
BKT Cylinder	(FAIR) · Attn				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE					
BKT (STD / SLOPE / NARROW / SKELETON / OTHER()					
Lever	LONG · (WRIST)				
Multi	(MULTI) · 2 · NO				
ARM-CRANE	(YES) · NO	クレーン用フック破損あり HOOK: BROKEN			
BLADE	YES · (NO)				
OFFSET	YES · (NO)				
OFFSET Cylinder	FAIR · Attn				
Piping	YES · (NO)	Breaker only · Multi			
COMMENT ワンタッチ付 W/ONE-TOUCH					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。