

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/6	MAKE	KOMATSU	MODEL	WA500-7		
SERIAL	70075		STAMP	NOT FOUND			
HR METER	18753	HR	Odometer	64328	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	29.5R25		

ENGINE : MODEL		6D140E-6	S/N	732174
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY			
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	Fコーキングあり WINDSHIELD: CAULKING	
AirCon	A/C	▪	H/C ▪ H only ▪ C only ▪ None	

FRONT & CYLINDERS

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	シリンダー油漏れあり CYLINDER: OIL LEAKING
Articulate	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

MISSION 周油漏れあり AROUND TRANSMISSION: OIL LEAKING

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	☒ YES	☐ NO
--------------	--------------------------------------	--------------------------

ATTACHMENTS

STD BKT	YES • OTHER	
---------	-------------	--

BLADE	YES	☒ NO	Piping for Tilt	YES	☒ NO
-------	-----	-------------------------------------	-----------------	-----	-------------------------------------

COMMENT

L03、L01表示あり(KDPF系統異常、作業機系統異常、システム異常)

"L03" & "L01" ERRORS DISPLAY

FOR DIESEL PARTICULATE FILTER SYSTEM, IMPLEMENTS, & SYSTEM

A/C動作しない A/C: NOT WORKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。