

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/9	MAKE	HITACHI	MODEL	ZX225USRLCK-3
SERIAL	HCM1U600J00205142			STAMP	HCM1U600J00205142
HR METER	10625	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 4HK1 **S/N**

Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	運転席左割れあり LEFT SIDE GLASS: BROKEN
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	2ピースブーム 2-PIECE BOOM
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	傷小 SCRATCHED
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

.....

.....

.....

.....

BKT STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

作動油漏れ小(場所不特定)

HYDRAULIC OIL LEAKING (LEAK SPOT: UNKNOWN)

A/C不良 A/C: MALFUNCTION

バックモニター不良 BACK MONITOR: MALFUNCTION

エラー、警告灯点灯あり WARNING DISPLAY, WARNING LAMP: ON

*1 油漏れ小(場所不特定) OIL LEAKING (LEAK SPOT: UNKNOWN)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。