

**INSPECTION SHEET 検品書**  
**ASPHALT FINISHER アスファルトフィニッシャー**

INSPECTION DATE	2025/8/22	MAKE	HANTA	MODEL	F1432W3
SERIAL	00190			STAMP	NOT FOUND
HR METER	5790	HR	YEAR	YR	
SHOE		TIRE (REAR)	255/80R22.5	MAX PAVING WIDTH	3200 mm

<b>ENGINE : MODEL S/N</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Oil leakage</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Blow-By</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td>A LITTLE ・ MIDDLE ・ SEVERE</td> </tr> <tr> <td>Sound</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES</td> <td style="text-align: center;">NO</td> <td></td> </tr> </table> <b>OPERATION PUMP</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Sound</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil leakage</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Power</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> <b>COOLING SYSTEM</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Radiator</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil Cooler</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table> <b>OPERATING SYSTEM</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">TRAVEL</td> <td style="width: 10%; text-align: center;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>SCREED(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SCREED(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>VIBRATION</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>TAMPER</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SPREADER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>SPREADER(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(R)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>HOPPER(L)</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>FEEDER</td> <td style="text-align: center;">FAIR</td> <td>Attn</td> <td></td> </tr> </table>	Oil leakage	FAIR	Attn		Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	Sound	FAIR	Attn		Oil	FAIR	Attn		Exhaust Color	FAIR	Attn		US EPA	YES	NO		Sound	FAIR	Attn		Oil leakage	FAIR	Attn		Power	FAIR	Attn		Radiator	FAIR	Attn		Oil Cooler	FAIR	Attn		TRAVEL	FAIR	Attn		SCREED(R)	FAIR	Attn		SCREED(L)	FAIR	Attn		VIBRATION	FAIR	Attn		TAMPER	FAIR	Attn		SPREADER(R)	FAIR	Attn		SPREADER(L)	FAIR	Attn		HOPPER(R)	FAIR	Attn		HOPPER(L)	FAIR	Attn		FEEDER	FAIR	Attn		<b>UNDERCARRIAGE : See Photos. 写真参照</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">3</td> </tr> <tr> <td>TIRE WEAR</td> <td>FAIR ・ <b>WORN</b> ・ UNEVEN WEAR</td> </tr> </table> <b>COMMENT</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div> <b>SCREED WIDTH</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">MAIN SCREED</td> <td style="width: 20%; text-align: center;">1.5</td> <td style="width: 40%; text-align: right;">m</td> </tr> <tr> <td>WITH AUTO-WIDENER</td> <td style="text-align: center;">3.2</td> <td style="text-align: right;">m</td> </tr> <tr> <td>WITH EXTENSION</td> <td></td> <td style="text-align: right;">m</td> </tr> </table> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">LEVEL SENSOR</td> <td style="width: 20%;">YES</td> <td style="width: 40%; text-align: center;">NO</td> </tr> </table> <b>COMMENT</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%; text-align: center;">3</td> </tr> </table>	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ <b>WORN</b> ・ UNEVEN WEAR	MAIN SCREED	1.5	m	WITH AUTO-WIDENER	3.2	m	WITH EXTENSION		m	LEVEL SENSOR	YES	NO	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Oil leakage	FAIR	Attn																																																																																																					
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE																																																																																																				
Sound	FAIR	Attn																																																																																																					
Oil	FAIR	Attn																																																																																																					
Exhaust Color	FAIR	Attn																																																																																																					
US EPA	YES	NO																																																																																																					
Sound	FAIR	Attn																																																																																																					
Oil leakage	FAIR	Attn																																																																																																					
Power	FAIR	Attn																																																																																																					
Radiator	FAIR	Attn																																																																																																					
Oil Cooler	FAIR	Attn																																																																																																					
TRAVEL	FAIR	Attn																																																																																																					
SCREED(R)	FAIR	Attn																																																																																																					
SCREED(L)	FAIR	Attn																																																																																																					
VIBRATION	FAIR	Attn																																																																																																					
TAMPER	FAIR	Attn																																																																																																					
SPREADER(R)	FAIR	Attn																																																																																																					
SPREADER(L)	FAIR	Attn																																																																																																					
HOPPER(R)	FAIR	Attn																																																																																																					
HOPPER(L)	FAIR	Attn																																																																																																					
FEEDER	FAIR	Attn																																																																																																					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																						
TIRE WEAR	FAIR ・ <b>WORN</b> ・ UNEVEN WEAR																																																																																																						
MAIN SCREED	1.5	m																																																																																																					
WITH AUTO-WIDENER	3.2	m																																																																																																					
WITH EXTENSION		m																																																																																																					
LEVEL SENSOR	YES	NO																																																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																						

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。