

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |                   |
|-----------------|----------------------------------------|------|---------|-------|-------------------|
| INSPECTION DATE | 2025/7/22                              | MAKE | HITACHI | MODEL | ZX135US-3         |
| SERIAL          | HCM1R400C00090011                      |      |         | STAMP | HCM1R400C00090011 |
| HR METER        | 813? ONES PLACE: UNREADABLE            | HR   | YEAR    | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |         | SHOE  | 500G PADS         |

|                           |       |      |                            |               |
|---------------------------|-------|------|----------------------------|---------------|
| ENGINE : MODEL            |       | 4JJ1 | S/N                        | 165212        |
| Oil leakage               | FAIR  | Attn |                            |               |
| Blow-By                   | FAIR  | Attn | A LITTLE • MIDDLE • SEVERE |               |
| Sound                     | FAIR  | Attn |                            |               |
| Oil                       | FAIR  | Attn |                            |               |
| Exhaust Color             | FAIR  | Attn |                            |               |
| US EPA                    | YES   | NO   |                            |               |
| MAIN PUMP                 |       |      |                            |               |
| Sound                     | FAIR  | Attn |                            |               |
| Oil leakage               | FAIR  | Attn |                            |               |
| Power                     | FAIR  | Attn |                            |               |
| COOLING SYSTEM            |       |      |                            |               |
| Radiator                  | FAIR  | Attn |                            |               |
| Oil Cooler                | FAIR  | Attn |                            |               |
| OPERATING SYSTEM          |       |      |                            |               |
| Swing                     | FAIR  | Attn | ガタあり SWING: LOOSE          |               |
| Travel                    | FAIR  | Attn |                            |               |
| INTERIOR See Photos. 写真参照 |       |      |                            |               |
| INTERIOR COND.            | CLEAN | FAIR | DIRTY                      |               |
| Operator's Seat           | FAIR  | Attn | 破れあり A LITTLE DAMAGED      |               |
| Glasses                   | FAIR  | Attn |                            |               |
| AirCon                    | A/C   | H/C  | H only                     | C only • None |
| BOOM / ARM / BKT          |       |      |                            |               |
| Boom                      | FAIR  | Attn |                            |               |
| Boom Cylinder             | FAIR  | Attn |                            |               |
| Arm                       | FAIR  | Attn |                            |               |
| Arm Cylinder              | FAIR  | Attn |                            |               |
| BKT                       | FAIR  | Attn |                            |               |
| BKT Cylinder              | FAIR  | Attn | ロッド傷あり ROD: SCRATCHED      |               |

|                                                                      |                                             |
|----------------------------------------------------------------------|---------------------------------------------|
| UNDERCARRIAGE : See Photos. 写真参照                                     |                                             |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                           |
| COMMENT                                                              |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| BKT                                                                  | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG • WRIST                                |
| Multi                                                                | MULTI • 2 • NO                              |
| ARM-CRANE                                                            | YES • NO *1                                 |
| BLADE                                                                | YES • NO                                    |
| OFFSET                                                               | YES • NO                                    |
| OFFSET Cylinder                                                      | FAIR • Attn                                 |
| Piping                                                               | YES • NO Breaker only • Multi               |
| COMMENT                                                              |                                             |
| A/C操作パネル何も操作できない(風も出ない)                                              |                                             |
| A/C OPERATION PANEL: MALFUNCTION, A/C: NOT BLOWING AIR               |                                             |
| Iリンク左アーム側ピン鉄筋棒、Iリンク: ガタつきあり                                          |                                             |
| ARM SIDE OF LEFT I-LINK LOCK PIN: IRON BAR, I-LINKS: LOOSE           |                                             |
| モニター一部表示不良 MONITOR: PARTLY NOT DISPLAYING                            |                                             |
| *1 モード入るがクレーン故障警告あり、フック欠                                             |                                             |
| *1 "3" & "4" ERRORS DISPLAY (CRANE MODE: ABLE TO TURN ON),           |                                             |
| NO HOOK                                                              |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                             |
| 4                                                                    |                                             |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。