

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/2	MAKE	KUBOTA	MODEL	U-20-3S
SERIAL	14324		STAMP	14324	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	250R	

ENGINE : MODEL						S/N	1CP2892
Oil leakage	(FAIR)	Attn					
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE				
Sound	(FAIR)	Attn					
Oil	(FAIR)	Attn					
Exhaust Color	(FAIR)	Attn					
US EPA	YES · (NO)						
MAIN PUMP							
Sound	(FAIR)	Attn					
Oil leakage	(FAIR)	Attn					
Power	(FAIR)	Attn					
COOLING SYSTEM							
Radiator	(FAIR)	Attn					
Oil Cooler	(FAIR)	Attn					
OPERATING SYSTEM							
Swing	(FAIR)	Attn					
Travel	(FAIR)	Attn					
INTERIOR See Photos. 写真参照							
INTERIOR COND.	CLEAN · (FAIR) · DIRTY						
Operator's Seat	(FAIR)	Attn					
Glasses	FAIR	Attn					
AirCon	A/C · H/C · H only · C only · (None)						
BOOM / ARM / BKT							
Boom	(FAIR)	Attn					
Boom Cylinder	(FAIR)	Attn					
Arm	(FAIR)	Attn					
Arm Cylinder	(FAIR)	Attn					
ATTACHMENT	(FAIR)	Attn					
BKT Cylinder	(FAIR)	Attn					

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT 左走行減速機周り油漏れ小 AROUND LEFT TRAVEL REDUCER: OIL LEAKING			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	YES · (NO)		
BLADE	(YES) · NO		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · (NO)	Breaker only · Multi	
COMMENT メーター故障あり METER: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。