

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/7/28	CATEGORY	除雪機(手押し) WALK-BEHIND SNOW PLOW		
MAKE	HONDA		MODEL	SB800 (SAMJ)	
SERIAL	1101417		STAMP	NOT FOUND	
HR METER	UNKNOWN	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	120R	TIRE

ENGINE	MODEL	S/N
Oil leakage	FAIR • Attn	Oil
Blow-By	FAIR • Attn	Exhaust Color
Sound	FAIR • Attn	EPA

CONDITION	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。