

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/23	MAKE	YANMAR	MODEL	VIO45-6
SERIAL	61902		STAMP	61902	
HR METER	5938	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	350G PADS	

ENGINE : MODEL		S/N	T1060
Oil leakage	<u>FAIR</u> • Attn		
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	<u>FAIR</u> • Attn		
Oil	<u>FAIR</u> • Attn		
Exhaust Color	<u>FAIR</u> • Attn		
US EPA	YES • <u>NO</u>		
MAIN PUMP			
Sound	<u>FAIR</u> • Attn		
Oil leakage	<u>FAIR</u> • Attn		
Power	<u>FAIR</u> • Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> • Attn		
Oil Cooler	<u>FAIR</u> • Attn		
OPERATING SYSTEM			
Swing	<u>FAIR</u> • <u>Attn</u>	ゴリゴリ感あり RATTLING	
Travel	<u>FAIR</u> • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY		
Operator's Seat	<u>FAIR</u> • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • <u>None</u>		
BOOM / ARM / BKT			
Boom	<u>FAIR</u> • Attn	ガタあり LOOSE	
Boom Cylinder	<u>FAIR</u> • Attn		
Arm	<u>FAIR</u> • Attn		
Arm Cylinder	<u>FAIR</u> • Attn		
BKT	<u>FAIR</u> • Attn		
BKT Cylinder	<u>FAIR</u> • Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	<u>YES</u> • NO Breaker only • <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。