

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/12	MAKE	CAT	MODEL	313DCR
SERIAL	CAT0313DPLCE00947		STAMP	CAT0313DPLCE00947	
HR METER	21494	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		C4.2	S/N
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
US EPA	YES • NO		
MAIN PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Swing	FAIR • Attn		
Travel	FAIR • Attn		
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn	切れあり CUT	
Glasses	FAIR • Attn	Fガラス割れあり WINDSHIELDS: CRACKED	
AirCon	A/C • H/C • H only • C only • None		
BOOM / ARM / BKT			
Boom	FAIR • Attn		
Boom Cylinder	FAIR • Attn		
Arm	FAIR • Attn		
Arm Cylinder	FAIR • Attn		
ATTACHMENT	FAIR • Attn		
BKT Cylinder	FAIR • Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
COMMENT			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG • WRIST		
Multi	MULTI • 2 • NO		
ARM-CRANE	YES • NO		
BLADE	YES • NO	自然降下 HYDRAULIC DRIFT	
OFFSET	YES • NO		
OFFSET Cylinder	FAIR • Attn		
Piping	YES • NO	Breaker only • Multi	
COMMENT			
電装系統異常あり(操作パネル作動しない)			
ELECTRICAL SYSTEM: MALFUNCTION (MONITOR: NOT WORK)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。