

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2025/9/1	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	HOKUETSU		MODEL	PDW300SLE II	
SERIAL	614C20-0512		STAMP	NOT FOUND	
HR METER	592	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	D905-E	S/N
Oil leakage	<input checked="" type="radio"/> FAIR ▪ Attn		Oil
Blow-By	<input checked="" type="radio"/> FAIR ▪ Attn	A LITTLE ▪ MIDDLE ▪ SEVERE	Exhaust Color
Sound	<input checked="" type="radio"/> FAIR ▪ Attn		Radiator

GENERATOR			
RATED POWER	9.9	KVA	Leaking Breaker Condition
RATED AMPERE	28.6 / 26	A	Insulation Condition
Output Terminal	<input checked="" type="radio"/> FAIR ▪ Attn		

COMPRESSOR			
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition
RATED AIR FLOW		m3/min	Receiver Tank Condition
Compressor Oil Leak	<input type="radio"/> FAIR ▪ Attn		Safety Valve Condition

CONDITION	<input checked="" type="radio"/> FAIR ▪ Attn	
未確認 OPERATION: NOT CHECKED		

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR
--	---	-----------	---------------------------

COMMENTS <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px solid black; height: 15px; margin-bottom: 5px;"></div>
--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。