

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/18	MAKE	KOMATSU	MODEL	PC08UU-1F
SERIAL	3676		STAMP	NOT FOUND	
HR METER	2128	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	180R	

ENGINE : MODEL								S/N	
Oil leakage		(FAIR)	Attn						
Blow-By		(FAIR)	A LITTLE · MIDDLE · SEVERE						
Sound		(FAIR)	Attn						
Oil		(FAIR)	(Attn)多い MUCH OIL						
Exhaust Color		(FAIR)	Attn						
US EPA		YES	(NO)						
MAIN PUMP									
Sound		(FAIR)	Attn						
Oil leakage		(FAIR)	Attn						
Power		(FAIR)	Attn						
COOLING SYSTEM									
Radiator		(FAIR)	Attn						
Oil Cooler		(FAIR)	Attn						
OPERATING SYSTEM									
Swing		(FAIR)	Attn						
Travel		(FAIR)	Attn						
INTERIOR See Photos. 写真参照									
INTERIOR COND.		CLEAN	· FAIR · (DIRTY)						
Operator's Seat		(FAIR)	(Attn)破れ大 TORN						
Glasses		(FAIR)	Attn						
AirCon		A/C	· H/C · H only · C only · (None)						
BOOM / ARM / BKT									
Boom		(FAIR)	Attn						
Boom Cylinder		(FAIR)	Attn						
Arm		(FAIR)	Attn						
Arm Cylinder		(FAIR)	Attn						
ATTACHMENT		(FAIR)	Attn						
BKT Cylinder		(FAIR)	Attn						
UNDERCARRIAGE :									See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								2	
COMMENT									
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()							
Lever	LONG	(WRIST)							
Multi	MULTI	· 2 · (NO)							
ARM-CRANE	YES	(NO)							
BLADE	(YES)	· NO							
OFFSET	(YES)	· NO *1							
OFFSET Cylinder	(FAIR)	Attn							
Piping	YES	(NO) Breaker only · Multi							
COMMENT									
E/Gフードへコミあり ENGINE HOOD: DENT									
CNP上部フレーム、カバーなし									
CNP TOP FRAME & CNP TOP: MISSING									
*1 足元ペダル固着ぎみ PEDAL: A LITTLE STUCK									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。