

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |      |       |          |
|-----------------|----------------------------------------|------|------|-------|----------|
| INSPECTION DATE | 2025/8/5                               | MAKE | KATO | MODEL | HD823MRV |
| SERIAL          | NO PLATE                               |      |      | STAMP | 5156     |
| HR METER        | 6909                                   | HR   | YEAR | YR    |          |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 600G     |

|                                              |                                        |
|----------------------------------------------|----------------------------------------|
| <b>ENGINE : MODEL</b> 4M50 <b>S/N</b> D56891 |                                        |
| Oil leakage                                  | FAIR · Attn 油污れ大 MUCH OIL STAINS       |
| Blow-By                                      | FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound                                        | FAIR · Attn                            |
| Oil                                          | FAIR · Attn                            |
| Exhaust Color                                | FAIR · Attn 白煙小 A LITTLE WHITE FUMES   |
| US EPA                                       | YES · NO                               |
| <b>MAIN PUMP</b>                             |                                        |
| Sound                                        | FAIR · Attn                            |
| Oil leakage                                  | FAIR · Attn                            |
| Power                                        | FAIR · Attn                            |
| <b>COOLING SYSTEM</b>                        |                                        |
| Radiator                                     | FAIR · Attn                            |
| Oil Cooler                                   | FAIR · Attn                            |
| <b>OPERATING SYSTEM</b>                      |                                        |
| Swing                                        | FAIR · Attn ガタ大 SWING: MUCH LOOSE      |
| Travel                                       | FAIR · Attn *1                         |
| <b>INTERIOR See Photos. 写真参照</b>             |                                        |
| INTERIOR COND.                               | CLEAN · FAIR · DIRTY                   |
| Operator's Seat                              | FAIR · Attn 破れあり MUCH WORN             |
| Glasses                                      | FAIR · Attn *2                         |
| AirCon                                       | A/C · H/C · H only · C only · None     |
| <b>BOOM / ARM / BKT</b>                      |                                        |
| Boom                                         | FAIR · Attn                            |
| Boom Cylinder                                | FAIR · Attn                            |
| Arm                                          | FAIR · Attn                            |
| Arm Cylinder                                 | FAIR · Attn 油漏れあり OIL LEAKING          |
| BKT                                          | FAIR · Attn ガタあり LOOSE                 |
| BKT Cylinder                                 | FAIR · Attn 傷あり SCRATCHED              |

|                                                                        |                                             |
|------------------------------------------------------------------------|---------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                                |                                             |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2         |                                             |
| <b>COMMENT</b>                                                         |                                             |
| 底板周り油漏れ小 BOTTOM: OIL LEAKING                                           |                                             |
|                                                                        |                                             |
| BKT                                                                    | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                  | LONG · WRIST                                |
| Multi                                                                  | MULTI · 2 · NO                              |
| ARM-CRANE                                                              | YES · NO                                    |
| BLADE                                                                  | YES · NO                                    |
| OFFSET                                                                 | YES · NO                                    |
| OFFSET Cylinder                                                        | FAIR · Attn                                 |
| Piping                                                                 | YES · NO Breaker only · Multi               |
| <b>COMMENT</b>                                                         |                                             |
| ブーム、アーム周りホースひび割れ多数あり                                                   |                                             |
| MANY HOSES AROUND BOOM & ARM: CRACKED                                  |                                             |
| CABドアラッチ掛からない DOOR LATCH: MALFUNCTION                                  |                                             |
| E/G冷却水レベル確認表示あり WARNING DISPLAY FOR COOLANT LEVEL                      |                                             |
| A/C画面表示薄い A/C MONITOR: BLURRED                                         |                                             |
| バックカメラ不良 BACK MONITOR: MALFUNCTION                                     |                                             |
| *1 左レバー戻り悪い LEFT TRAVEL LEVER: HARD TO RETURN                          |                                             |
| *2 F下部ガラス欠、フレームサビ多数、Fガラス上げたまま固着あり                                      |                                             |
| *2 LOWER WINDSHIELD: MISSING, FRAME: MUCH RUSTY,                       |                                             |
| UPPER WINDSHIELD FRAME: STUCK AT THE CEILING POSITION                  |                                             |
|                                                                        |                                             |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1 |                                             |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。