

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/28	MAKE	SUMITOMO	MODEL	SH200-7
SERIAL	SMT200A7H00SC4148			STAMP	SMT200A7H00SC4148
HR METER	1510+9	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 4HK1 **S/N** 849995

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

E/G回転上がらない UNABLE TO REV UP
A/C効かない A/C: MALFUNCTION
遠隔操作のモニターと配線はあるが操作盤がない
NO CONTROL PANEL (W/REMOTE CONTROL MONITOR & WIRING)

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO *1

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

水没機(淡水)(コントロールユニット、コントローラー、モニター交換あり)
SUBMERGED MACHINE(FRESH WATER)
(CONTROL UNIT, CONTROLLER, & MONITOR: REPLACED)
HRメーター1510時間の時に水没によりモニター交換(メーカー確認済)
HR METER: REPLACED AT 1510HR DUE TO SUBMERSION
(INFORMATION BY SUMITOMO)

警告灯点灯ありWARNING LAMPS FOR EXHAUST SYSTEM & NO POWER: ON

警告表示あり(初期設定未完了、E/G系統異常、SCR系統異常)

WARNINGS DISPLAY FOR SETUP INCOMPLETE, ENGINE, & SCR SYSTEM

ピーピーピーと音が鳴る WARNING SOUNDS: ON

*1 クレーン操作は正常だが画面表示が出ない

*1 LOAD INDICATOR: NOT DISPLAYING (CRANE: ABLE TO OPERATE)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。